

# Underground Storage Tanks (USTs) Public Record - Summary Information

## General Information

Public Record Posted Date: 11/13/2015

Total Number Of Active UST Facilities: 7,907  
 Total Number Of USTs: 25,368

## Summary Information For On-Site Inspections

Number Of UST Facilities Inspected: 3,598  
 Inspection Period Dates: 10/1/2014 To: 9/30/2015  
 Percent Compliance (Combined Measure): 63%

Note: Tank, facility, and on-site inspection information is based on registered regulated Underground Storage Tanks. On-site inspections measure compliance with SOC (Significant Operational Compliance - compliance with federal release detection and release prevention requirements).

## Summary Information For Releases

Number Of Confirmed UST Releases: 227  
 Release Reporting Period Dates 10/1/2014 To: 9/30/2015

## Summary Information For Release Sources And Causes

| Source           |     |      | Cause |    |          |    |           |     |                  |     |                 |    |       |    |         |     |
|------------------|-----|------|-------|----|----------|----|-----------|-----|------------------|-----|-----------------|----|-------|----|---------|-----|
|                  |     |      | Spill |    | Overfill |    | Corrosion |     | Phys/Mech Damage |     | Install Problem |    | Other |    | Unknown |     |
| #                | %   |      | #     | %  | #        | %  | #         | %   | #                | %   | #               | %  | #     | %  | #       | %   |
| Tank             | 133 | 59%  | 2     | 2% | 3        | 2% | 48        | 36% | 13               | 10% | 0               | 0% | 2     | 2% | 65      | 49% |
| Piping           | 19  | 8%   | 1     | 5% | 0        | 0% | 2         | 11% | 6                | 32% | 0               | 0% | 1     | 5% | 9       | 47% |
| Dispenser        | 42  | 18%  | 3     | 7% | 1        | 2% | 6         | 14% | 14               | 33% | 0               | 0% | 1     | 2% | 17      | 40% |
| STP**            | 0   | 0%   | 0     | 0% | 0        | 0% | 0         | 0%  | 0                | 0%  | 0               | 0% | 0     | 0% | 0       | 0%  |
| Delivery Problem | 0   | 0%   | 0     | 0% | 0        | 0% | 0         | 0%  | 0                | 0%  | 0               | 0% | 0     | 0% | 0       | 0%  |
| Other            | 2   | 1%   | 0     | 0% | 0        | 0% | 0         | 0%  | 1                | 50% | 0               | 0% | 0     | 0% | 1       | 50% |
| Unknown          | 31  | 14%  | 0     | 0% | 0        | 0% | 0         | 0%  | 2                | 6%  | 0               | 0% | 0     | 0% | 29      | 94% |
| Totals           | 227 | 100% | 6     |    | 4        |    | 56        |     | 36               |     | 0               |    | 4     |    | 121     |     |

Note: Release, source and cause information is based on data from regulated tanks. Source and cause data were collected primarily using forms and reports submitted by Responsible Parties or their agents.

\*Additionally, there were 558 confirmed releases from non-regulated USTs, primarily heating oil tanks, during the reporting period.

\*\*STP - Submersible Turbine Pump

To obtain site-specific information on UST releases contact the Regional DENR Office for the county in which the release occurred. To obtain UST compliance information contact the UST Section Central Office.